

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	8321	(adjust\$4 test\$4 analy\$4 evaluat\$4 examin\$4 study\$4 sens\$4 detect\$4 transducer measur\$4) near3 ( axial\$4 ) near3 (force load strain stress pressure )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:22
L2	1109	1 and (bolt nut fasten\$4 screw\$4). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:25
L3	267	2 and (thread ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:25
L4	31	3 and (washer ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:23
L5	10	4 and (electrical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:24
L6	7	5 and (spring )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:26
L7	5	6 and (signal )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:14
L8	1359	(adjust\$4 test\$4 analy\$4 evaluat\$4 examin\$4 study\$4 sens\$4 detect\$4 transducer measur\$4) near3 ( axial\$4 ) near3 (force load strain stress pressure ) .clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:15
L9	64	8 and (washer ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:25

## EAST Search History

L10	36	9 and (bolt nut fasten\$4 screw\$4). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:23
L11	21	10 and (thread )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:23
L12	5	11 and (electrical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:15
L13	4434	1 and (bolt nut fasten\$4 screw\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:25
L14	1568	13 and (thread )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:25
L15	457	14 and (washer )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:18
L16	125	15 and (electrical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 10:41
L17	22	16 and (acoustic optic\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 11:47
L18	16	17 and (wire pin )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:13

## EAST Search History

L19	86	(adjust\$4 test\$4 analy\$4 evaluat\$4 examin\$4 study\$4 sens\$4 detect\$4 transducer measur\$4) near3 ( axial\$4 ) near3 (force load strain stress pressure ) near3 (screw\$4 nut bolt fasten\$4 ) .clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:22
L20	29	19 and (washer )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:18
L21	18	20 and (wire pin )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:18
L22	6	21 and (electrical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:18
L23	21	19 and (electrical\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:23
L24	12	23 and (pin wire )	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/04/28 12:23